

Aircraft For Sale  
2006 Challenger 300



FILE FOTO

PYXIS  
AVIATION  
GROUP  
navigating the deal





2006 Bombardier Challenger 300  
SN 20079

## Summary

- Registered OE-HOO
- Serial Number 20079
- Total hours 6,637
- Total cycles 3,117
- JAR OPS 1 compliant
- Engines & APU on JSSI (enrolled since 1,125h)
- On CAMP since new
- 9 Passenger configuration



## Engines

Engine Type:	Honeywell – AS907	
	#1	#2
Hours:	6,637	6,637
Cycles:	3,117	3,117



## APU

Type:	Honeywell GTCP36-150(BD)	
Hours:	5,230	
Cycles:	672	





2006 Bombardier Challenger 300

SN 20079

## Avionics

- Rockwell Collins Proline 21
- Single Collins TTR-4000 TCAS Computer
- FDR
- CVR
- Dual Collins FMS
- Dual Collins Radio Altimeter
- Triple Collins IRS IRU
- Single Radar Altimeter
- Dual Global Positioning System Receivers
- Single Collins Weather Radar
- Single Avitec SELCAL
- Dual Collins 9031A HF
- Triple Collins 4000 VHF
- Dual Collins Transponders
- Dual Collins NAV Receivers
- Dual Collins VOR/LOC Antennas
- Dual Collins ADF Receivers
- Dual Collins DME Transceivers



## Options

- High intensity table/reading lights throughout each sitting area
- Iridium satellite phone
- Two 12 man liferafts under divan
- Coat rack and dropdown storage in aft baggage compartment






2006 Bombardier Challenger 300

SN 20079

## Interior

- 9 passengers
- Single 3 place divan
- Dual forward club
- Three pull-out tables
- Dual Rosen LCD monitors
- Airshow
- DVD/CD Entertainment system (remote controlled)
- Audio-video amplifier
- Aft lavatory
- Galley with microwave and coffee maker



# PYXIS AVIATION GROUP

navigating the deal



2006 Bombardier Challenger 300

SN 20079





2006 Bombardier Challenger 300

SN 20079

## Exterior

White lower fuselage with tan upper half, light and dark brown separating stripes.



## Contact Details:

Mark Cobb [mc@pyxis.aero](mailto:mc@pyxis.aero) +43 67683211451

Specifications and/or descriptions are provided as introductory information. They do not constitute representations or warranties of Pyxis Aviation Group. You should rely on your own inspection of the aircraft.