

SPECIFICATIONS - As of OCT 2024

BOMBARDIER GLOBAL 5000 SN9534 OE-LHU









DELIVERY YEAR

TOTAL TIME

LANDINGS

2013

6,696

1,660



AIRCRAFT NOTABLE FEATURES

- > Vision Cockpit
- > 10C Inspection Completed in 2023
- > EASA EU OPS1 Compliant

- MTOW increase to 92,500lbs
- > HUD / EVS
- > CPDLC, ADSB-Out, TCAS 7.1



INTERIOR

High Ticket Full Interior Refurbishment Completed in 2023

SPECIFICATION - BOMBARDIER GLOBAL 5000 9534



Airframe		
Delivery Year	2013	
Registration	OE-LHU	
Serial Number	9534	
Total Airframe Hours	6,696	
Landings	1,660	
Location	Doha	
Engines		
ROLLS-ROYCE DERBY PLC	ENGINE 1	ENGINE 2
Serial Number	22195	22194
Time Since New	6,696	6,696
Cycles Since New	1,669	1,669

APU	
Description	Honeywell RE 220
Serial Number	P-662
Time Since New	4,776
APUS	3,907

Avionics	Model	QTY
VOR/ILS/MB/ADF RECEIVER	NAV-4000	2
DME TRANSCEIVER	DME-4000	2
VHF COM TRANSCEIVER	VHF-4000	2
VHF COM TRANSCEIVER	VHF-4000	1
TRAFFIC SURVEILLANCE SYSTEM	TSS-4100	1
MODE-S TRANSPONDER	TDR-94D	1
HF TRANSCEIVER	HF-9031A	2
RADIO ALTIMETER	ALT-4000	2
GPS TRANSCEIVER	GPS-4000S	2
WEATHER RADAR	RTA-4118	1
SATELLITE DATA UNIT	SDU-2200-2	1
EMERGENCY LOCATING TRANSMITTER	B406-4	1
DUAL CHANNEL IRIDIUM CSU - ITCS	ASPIRE 100	1
INERTIAL REFERENCE UNIT	IR-600 (Laser Ref VI)	3
FLIGHT DATA RECORDER	FA2100	1
COCKPIT VOICE RECORDER	FA2100	1

Interior	
Configuration	13 Passengers
Interior	2023
Forward Cabin	4 x Executive Club Seat Arrangement
Mid Cabin	4 x Place Conference Arrangement opposite a Credenza
Aft Cabin	2 x Executive Club Seat opposite a 3 x Place Divan
Galley	Nespresso Machine, Convection Oven, Microwave Oven, Cooler
Lavatories	Front Crew Lavatory, Aft Executive Lavatory
Connectivity	Viasat KU-Band Wifi
Paint Scheme	Matterhorn White, with grey and beige accents
Paint	2013



























Contact

Vadim Araslanov Managing Director

Phone: +43 676 832 11 451 E-mail: v.araslanov@pyxis.aero

www.pyxis.aero

Notes

Specifications, descriptions, terms, and pricing are provided as introductory information only. Interested parties should rely upon their own inspections and examinations of aircraft and their records. This introductory information is subject to changes and/or correction and does not constitute representations or warranties by Pyxis Aviation Group or its clients. This material does not represent a binding offering, and aircraft are subject to prior sale and/or withdrawal from the market at any time.